

# Contents

<b>1</b>	<b>Introduction</b>	<b>1</b>
1.1	Motivation . . . . .	2
1.2	Research Hypothesis . . . . .	2
1.3	Objectives . . . . .	2
1.3.1	General Objective . . . . .	2
1.3.2	Specific Objectives . . . . .	3
1.4	Scope of the Thesis . . . . .	3
<b>2</b>	<b>Theoretical Background</b>	<b>4</b>
2.1	Materials Characterization of Solar Photovoltaic Modules . . . . .	5
2.1.1	The Solar Cell . . . . .	5
2.1.2	Solar Modules Components . . . . .	7
2.2	Electrical Characterization of Solar Photovoltaic Modules . . . . .	10
2.2.1	The Diode Model . . . . .	10
2.3	Detection and Diagnosis of Failures/degradation Modes in Solar PV Modules . . . . .	13
2.3.1	Failure/Degradation Modes in Solar PV Modules . . . . .	13
2.3.2	Analysis of Field Testing Data . . . . .	17
2.4	Review of Field Test Campaign in the Atacama Desert . . . . .	22
2.4.1	Summary of Results from Previous Work . . . . .	22
2.5	Methodology . . . . .	24
2.6	Summary . . . . .	26
<b>3</b>	<b>Analysis of failure/degradation modes found in photovoltaic modules operating in the Atacama desert</b>	<b>28</b>
3.1	Front Cover Glass . . . . .	29
3.1.1	Soiling . . . . .	29
3.1.2	Heavily Soiled Modules . . . . .	32
3.1.3	Heavily Soiled Modules Before and After Cleaning . . . . .	38
3.1.4	Lightly Soiled Modules . . . . .	42
3.1.5	Milky Discoloration . . . . .	46
3.1.6	Materials Analysis of Failures Related to Front Cover Glass . . . . .	51
3.2	EVA Encapsulant . . . . .	52
3.2.1	Delamination . . . . .	52
3.2.2	Materials Analysis of Failures Related to EVA Encapsulant . . . . .	56
3.3	Solar Cells . . . . .	56
3.3.1	Partial Shading . . . . .	56

3.3.2	Hotspots . . . . .	62
3.3.3	Materials Analysis of Failures Related to Solar Cells . . . . .	66
3.4	Other Failures . . . . .	68
3.4.1	Faulty Soldering . . . . .	68
3.4.2	Cell Fracture . . . . .	68
3.5	Discussion and Recommendations for Future Work . . . . .	69
<b>4</b>	<b>Conclusions</b>	<b>74</b>
	<b>Bibliography</b>	<b>76</b>