

Contents

1	Introduction	1
1.1	Motivation	1
1.2	Objectives and scope	4
1.2.1	General objective	4
1.2.2	Specific objectives	4
1.2.3	Scope	4
2	Theoretical Background	5
2.1	Heat transfer	5
2.1.1	Poisson's equation	6
2.2	Splines	7
2.2.1	Finite Element Method	12
2.2.2	IsoGeometric Analysis (IGA)	13
2.2.3	Geometry-Independent Field approximaTion (GIFT)	14
2.3	Measurement of errors	17
2.3.1	L^2 -Norm	18
2.3.2	H^1 -Norm	18
2.3.3	Error indicators	18
2.3.4	Refinement strategy	19
3	Methodology and Resources	20
3.1	Methodology	20
3.2	Resources	21
4	Definition of The problems	22
4.1	Poisson's problem	22
4.2	Two Heat source problem	24
4.3	Geometry parameterization	26
5	Results	28
5.1	Poisson's problem	29
5.1.1	Method 1: L^2 -norm error indicator	29
5.1.2	Method 2: Residual based error indicator	37
5.1.3	Method 3: Hierarchical Adaptivity error indicator	42
5.2	Two Heat source problem	51
5.2.1	Method 1: L^2 -norm error indicator	51
5.2.2	Method 2: Residual based error indicator	58

5.2.3	Method 3: Hierarchical Adaptivity error indicator	63
5.3	Dependence of the solution on the parameterization of the geometry	72
6	Discussion	75
	Conclusion	76
	Bibliography	78